

MAHNCKE PARK RETAINING WALL

AFTER



BEFORE



DESCRIPTION:

The project here was to clean up an eroding hillside in front of this Mahncke Park home. The improvements here included:

- Leveling the top of the hill
- Regrading the slope of the hill
- Building two tiered concrete retaining walls to hold a new cactus garden

WIESEHEFTY
DESIGN • BUILD